



# Sorbothane® Isolation Pads



Sorbothane® Isolation Pads can support a wide range of loads. Select the correct thickness, durometer and the number of pads required for the load.


## ISOLATION PADS Square



PART NUMBER	DIMENSION	DURO	RATED LOAD (lbs)	NOTES
0510610-30-10	0.10 x 0.50 x 0.50	30	1 - 2	
0510610-50-10	0.10 x 0.50 x 0.50	50	3 - 6	
0510610-70-10	0.10 x 0.50 x 0.50	70	10 - 25	
0510618-30-10	0.188 x 0.50 x 0.50	30	0.5 - 1	
0510618-50-10	0.188 x 0.50 x 0.50	50	1.5 - 2.5	
0510618-70-10	0.188 x 0.50 x 0.50	70	5 - 14	
0510625-30-10	0.25 x 0.50 x 0.50	30	0.4 - 1.8	
0510625-50-10	0.25 x 0.50 x 0.50	50	1 - 2	
0510625-70-10	0.25 x 0.50 x 0.50	70	4 - 10	
0510712-30-10	0.125 x 0.75 x .0.75	30	3 - 6	
0510712-50-10	0.125 x 0.75 x .0.75	50	9 - 19	
0510712-70-10	0.125 x 0.75 x .0.75	70	37 -90	
0510718-30-10	0.188 x 0.75 x 0.75	30	1.5 - 3.5	
0510718-50-10	0.188 x 0.75 x 0.75	50	5 - 10	
0510718-70-10	0.188 x 0.75 x 0.75	70	20 - 50	
0510725-30-10	0.250 x 0.75 x 0.75	30	1 - 2.5	
0510725-50-10	0.250 x 0.75 x 0.75	50	3.5 - 7.5	
0510725-70-10	0.250 x 0.75 x 0.75	70	15 - 35	
0511012-30-10	0.125 x 1.00 x .100	30	9 - 18	
0511012-50-10	0.125 x 1.00 x .100	50	25 - 55	
0511012-70-10	0.125 x 1.00 x .100	70	100 - 270	
0511018-30-10	0.188 x 1.00 x .100	30	4.5 - 9.5	
0511018-50-10	0.188 x 1.00 x .100	50	13 - 28	
0511018-70-10	0.188 x 1.00 x .100	70	55 - 135	
0511025-30-10	0.250 x 1.00 x .100	30	3 - 6	
0511025-50-10	0.250 x 1.00 x .100	50	9 - 18	
0511025-70-10	0.250 x 1.00 x .100	70	36 - 90	

## ISOLATION PADS


with Fabric Top & Bottom



PART NUMBER	DIMENSION	DURO	RATED LOAD (lbs)	NOTES
0510425-30-10	0.25 x 2.5 x 2.5	30	NA	
0510425-50-10	0.25 x 2.5 x 2.5	50	NA	
0510425-70-10	0.25 x 2.5 x 2.5	70	NA	

## ISOLATION PADS

with PSA



PART NUMBER	DIMENSION	DURO	RATED LOAD (lbs)	NOTES
0510611-30-10	0.10 x 0.50 x 0.50	30	1 - 2	
0510611-50-10	0.10 x 0.50 x 0.50	50	3 - 6	
0510611-70-10	0.10 x 0.50 x 0.50	70	10 - 25	
0510619-30-10	0.188 x 0.50 x 0.50	30	0.5 - 1	
0510619-50-10	0.188 x 0.50 x 0.50	50	1.5 - 2.5	
0510619-70-10	0.188 x 0.50 x 0.50	70	5 - 14	
0510626-30-10	0.25 x 0.50 x 0.50	30	0.4 - 0.8	
0510626-50-10	0.25 x 0.50 x 0.50	50	1 - 2	
0510626-70-10	0.25 x 0.50 x 0.50	70	4 - 10	
0510713-30-10	.125 x 0.75 x 0.75	30	3 - 6	
0510713-50-10	.125 x 0.75 x 0.75	50	9 - 19	
0510713-70-10	.125 x 0.75 x 0.75	70	37 - 90	
0510719-30-10	.188 x 0.75 x 0.75	30	1.5 - 3.5	
0510719-50-10	.188 x 0.75 x 0.75	50	5 - 10	
0510719-70-10	.188 x 0.75 x 0.75	70	20 - 50	
0510726-30-10	.250 x 0.75 x 0.75	30	1 - 2.5	
0510726-50-10	.250 x 0.75 x 0.75	50	3.5 - 7.5	
0510726-70-10	.250 x 0.75 x 0.75	70	15 - 35	
0511013-30-10	.125 x 1.00 x 1.00	30	4 - 18	
0511013-50-10	.125 x 1.00 x 1.00	50	25 - 55	
0510813-70-10	.125 x 1.00 x 1.00	70	110 - 270	
0511019-30-10	.188 x 1.00 x 1.00	30	4.5 - 9.5	
0511019-50-10	.188 x 1.00 x 1.00	50	13 - 28	
0511019-70-10	.188 x 1.00 x 1.00	70	55 - 135	
0511026-30-10	.250 x 1.00 x 1.00	30	3 - 6	
0511026-50-10	.250 x 1.00 x 1.00	50	4 - 18	
0511026-70-10	.250 x 1.00 x 1.00	70	36 - 90	